

GREAT SALT LAKE MINERALS CORPORATION

P.O. BOX 1190 765 NORTH 10500 WEST OGDEN, UTAH 84402 TEL. (801) 731-3100 FAX (801) 731-4881



M/057/002

Kenneth A. Glauser
Chief Design Engineer

January 11, 1993

Mr. D. Wayne Hedberg, Permit Supervisor
State of Utah
Department of Natural Resources
Division of Oil, Gas, and Mining
355 W. North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Dear Mr. Hedberg:

Submitted herewith is the 1992 Annual Report of Mining Activities including a new drawing No. 101-091-05-036, West Lake Pond, Strong's Knob contour map, after excavation, April 29, 1992. Other drawings submitted with the 1991 annual report have not changed.

Regards,

A handwritten signature in black ink, appearing to read 'K.A. Glauser'.

K.A. Glauser

/mcb

Enclosure

*140 acres
on bond -*

*162.5 on this
report -*

RECEIVED

JAN 15 1993

DIVISION OF
OIL, GAS & MINING

Gilbert bond

25% cotton

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) Jan. 92 To (mo./yr.) Dec. 92
2. DOGM File Number: M / 057/ 002
3. Mine Name: Great Salt Lake Minerals Corporation
4. Mineral(s) Mined: Rock & Gravel
5. Legal Description (Location of Lands Affected): Refer to Drawing 800-11-05-027
Dated 2/13/92 Submitted last year.
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
6. Name of Operator or Company: Great Salt Lake Minerals Corporation
7. Permanent Address: 765 N. 10500 W.
Ogden, UT 84404

8. Company Representative (or designated operator):

Name: Max J. Reynolds
Title: VP/Operations
Address: P.O. Box 1190, Ogden, UT 84402
Phone: (801) 731-3100

- ☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 391,250 c.y.
3. How much new or additional acreage was affected during past year? 8.5 approx.
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
Approximately 8.6 acres were disturbed at the Strong's Knob
gravel and rock quarry pit to borrow material to complete construction
of the 8.5 mile dike near Lakeside as described in the amended
M/057/002. 391,250 c.y. of material was removed.
5. How much acreage was reclaimed during past year? 22.6 ac.
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
See Item 11.6 Continued.

7. What is the total disturbed acreage at years end? 162.5
(22.6 ac. total was disturbed at Strong's Knob Pit in 1991
and 1992).
8. Briefly summarize mining and reclamation planned for the upcoming year.
No further reclamation is planned

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): K.A. Glauser

Title of Operator: Chief Engineer

Signature of Operator: 

Date: 1/11/93

jb
MR-AR

Item 11.6 Continued

The Strong's Knob borrow pit, which was added on the amendment, had a total of 22.6 acres. of disturbed area in 1991 and 1992. 13.2 acres was in the all rock area and was terraced and shaped during construction to meet the Reclamation Plan requirement. 9.4 acres was located in the area of sand and used to crush rock for road base as well as borrowing sand for road surface. The area was shaped and graded to similar to original condition. There still remains some stockpiled material for future use for dike maintenance. Other than Strong's Knob, no reclamations in the other areas have been done. Natural growth of vegetation continues to cover these areas.

Refer to Drawing No. 101-01-05-036 for Strong's Knob Contour Map after excavation.